

Received 7/28/72

CONTRA-JET

D. S. TANABE

7920 49TH AVENUE SOUTH ☐ SEATTLE, WASHINGTON 98118 ☐ PHONE: PA 5-8322

92.94 m
(P) Set - comments?

17 July 1972

Remington Arms Co., Inc.
939 Barnum Avenue
Bridgeport, Conn. 06602

Gentlemen:

The Contra-Jet muzzle brake has been readily installed on many different models and calibers of Remington high power rifles with only one exception known to date: the Model 600 Carbine in .35 caliber. The barrel diameter at the muzzle of this particular rifle was found to be 0.530 inches----too small for installing the brake.

The brake cannot be readily installed if the muzzle diameter of the barrel, concentric with the bore, is much less than the preferred diameters set forth in the enclosed blue specs sheet for the various calibers.

Please check into your factory standards and inform me whether or not any other high power rifle, including possibly any future model, has or would have the muzzle diameter too small for readily installing the brake.

Thank you for your cooperation.

Sincerely yours,

Danabe

D. S. Tanabe

Encl

folder
specs

RECEIVED
JUL 28
CONSUMER SERVICES

RECEIVED
JUL 27 1972
OFFICE - F. E. MORGAN

Blue M/600
308 Win.
222 Rem.
6MM Rem.
223 Rem.
243 Win.
All other
models appear
to be O.K.