

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

*Remington*  
SPORT

*PETERS*  
SPORT

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" \_\_\_\_\_

July 28, 1972

TO: L. FOX

FROM: H. K. BOYLE/D. J. ANDERSON

TRIP REPORT

Places visited: Jerry's Sport Center, Olyphant, Pa. 7/24/72  
E. L. Blair & Son Sporting Goods,  
Williamsport, Pa. 7/25/72

Reference: M/700 Quality Complaint

1. Scope holes in Receiver out of alignment--  
can't bore sight rifles with a collimator.
2. Visual defects.

D. J. Anderson, Process Engineer; W. B. Cockman, Field Representative;  
and the writer visited the following establishments and reviewed the  
referenced M/700 Quality Complaints:

Jerry's Sport Center, Olyphant, Pa. - Jerry Warsky, Distributor-Jobber.

Mr. Warsky stated that M/700 rifles were unable to be collimated  
when equipped with a Leupold 3x-9x variable power scope mounted  
with fixed Weaver rings and mounts. Two (2) M/700 BDL, 30-06 Cal.  
rifles and one (1) Leupold 3x-9x scope were selected from Mr.  
Warsky's inventory and collimated satisfactorily. One (1) of the  
original complaint guns was selected and collimated satisfactorily  
with the Leupold scope. All three (3) guns were successfully targeted  
with live ammunition for point of impact; however, one (1) had very  
little additional windage or elevation adjustment remaining.

The visual items observed on the returned guns were reviewed and  
the program for corrective action discussed.

E. L. Blair & Son, Williamsport, Pa. - Sporting Goods Dealer (retailer)

Mr. Blair verified that the Leupold 3x-9x variable power scope and Weaver fixed rings and mounts were the primary problem although the Redfield 3x-9x variable power and the Redfield 4x have also been incapable of sighting in at times. He estimated that about 40% of the M/700-Leupold-Weaver combination could not be collimated as assembled and that shim stock was necessary for proper targeting. When shimming was necessary it was always applied to the left side of the rear base. Of the five (5) guns originally returned to Ilion by Mr. Blair and hand carried to his gunshop by this writer, two (2) could not be collimated with a Leupold 3x-9x scope selected from his inventory.

Comments and Observations:

The Leupold 3x-9x variable power scope has only 28 inches total windage and elevation adjustment ( $\pm$  14 inches). This is only about 1/3 of the adjustment available in other hunting scopes. Because adjustment appears to be limited in one direction only, the Leupold Company should be contacted on this matter.

Mr. Warsky and Mr. Blair are both good friends of Remington, and they appeared glad that such attention was being given to M/700 quality. They pointed out that Remington has the major portion of the centerfire rifle market and practically all of the shotgun market.

HKB/DJA/bd