

REMINGTON ARMS COMPANY, INC. - ILION WORKS
Investigator's Copy of Suggestion

NAME: GEORGE PROSSER 82 20692
ARMS WORKS 82 84443

SUGGESTION NO: 73-1326

CLOCK NO: _____

DATE RECEIVED: 1-19-73

M/580-1-2; 591-2; 788 Trigger Housing Assembly. Change design of Safety and Sear. Alter the M/540X Sear to provide a notch to control engagement between the Sear and Trigger which will not affect its use on the M/540X. Alter the M/580 & 788 Safety to function like the M/540X with the Sear instead of actuating a Safety Plunger. Make minor change to M/580 & 788 Housing to provide clearance for the M/540X type Sear and substitution of the M/540X Safety Plunger as Spring for the M/580 & 788 Safety Plunger and Spring. (NOTE: RD has marked prints). Eliminate Trigger Housing Sub Assy Op. 710-12-153. Eliminate scrap that is now produced at Op. #10. Improve quality by reducing play between Sear and Trigger.

SUPERVISION -

This Suggestor is a member of your area. PLEASE GIVE THIS YOUR PROMPT ATTENTION AND COMMENTS.

If the Suggestion should not be adopted, please write your detailed reasons, as the Suggestor deserves every consideration possible.

If it is adaptable, you are expected to expedite its installation or contact the respective Section (Engineering, Production, Safety, PE&C, etc.) for approval or assistance.

When it is in effect, return all answers to the Suggestion Committee Secretary.

S. P. Alvis - 2/6/73

you comments please !

*Report made and auto being initiated to check situation
and safety aspects. Research has been completed and a minor
change and cleanup on both models. I design agreed to it
will get economic evaluation*

R. H. Brown 2/6/73

RD-6562

R. H. Brown / MEB
Secretary, Suggestion Committee