FROM S. M. AIVIG

MODEL 700 - INSTRUCTION FOLDER

... M.H. Walker has requested change to the folder to indicate "No Trigger Adjustments Are Recommended".

This is in accordance with his consultation with F.E. Morgan. It is understood that the need arises as result of significant increase in customer complaints of problem growing out of attempts to adjust trigger by shooters. The designers believe this condition arises as result of differences in parts as compared to earlier production, with the sear being a contributor.

M.H. Walker advises that F.E. Morgan desires to see proof copy of the folder change before printing, and advice as to inventory in terms of usage requirements and inventory cost in order to determine whether this should be made without obsolescence.

SMA:T

cc: M.II. Walker F. E. Morgan

C1U