

cc: F.E. Morgan
J. Brooks
E.J. Giner

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE



4/27 - screws ordered & rec'd.

Bridgeport, Connecticut
April 26, 1973

M. Walker
Ilion

AUSTRALIAN 700 and 541 TRIGGER ADJUSTMENTS

At the same time I received your letter of April 24 suggesting the solution of the above problem, the following cable came to my office, "200 screws required for 100 only 700 and 12 only for 6 only 541."

In your absence we had a conference call with F.E. Morgan, John Brooks and the writer. It was agreed that Ilion would supply the parts required and the instructions needed to make this adjustment. The 541 solution is not as positive as the 700 but I suggest we send them the longer screw and hope that this satisfies the customs official.

Upon completion of the screws will you please air parcel post them and the installation instructions to the following address:-

BOUSTEAD WOOD PTY. LTD.
BOX 148
ERMINGTON 2115, AUSTRALIA
ATTN: D. TIETJEN, MANAGER

We want to thank you for your assistance in this matter and would appreciate a call from Ilion advising us when the parcel is posted for shipment.

ESC/ca

E.S. CIPER
E.S. CIPER
Manager
International Operations