

Model Shop Work Load As of 7-22-74

<u>WORK ON HAND</u>	<u>DATE REQ.</u>	<u>EST. COMP.</u>	<u>DAYS BEHIND</u>
<u>1100</u> Action Bar Sleeves	8-14	7-26	
<u>3200</u> Trigger Guards	7-25	7-25	
Vent Ribs	8-12	8-20	6
Ejector Spring	8-13	8-13	
Top Lock Lever Screw	7-15	7-25	8
Choke Blanks	8-15	8-16	1
Extractor Sear	7-26	7-26	
<u>1100X</u> Ejector Blanks	7-24	7-25	1
Spacer	8-16	8-13	
Connector Assembly	7-18	7-26	5
Sear Spring	7-26	7-26	
Friction Ring	7-25	7-25	
Port Cover Cam Pin	7-22	7-24	2
Feed latch Spring	8-12	8-12	
Top Lock Lever Spring	7-15	7-25	8
Top Lock Lever	7-26A	7-26	5
Trigger Plate Ret. Plunger	8-14	7-24	
Feed latch Spring	8-19	8-12	
Shell Cut-off Latch	7-18	7-25	5
Gas Cylinders		8-14	
<u>788</u> Bolt Plug	7-26	7-26	
Bolt Assembly	7-26	7-26	
Firing Pin	7-26	8-13	2
Firing Pin Head	7-26	8-13	2
<u>572</u> Firing Pin	7-19	7-23	1
<u>Wonder II</u> Components	9-1	8-16	

Model Shop Work Load As of 7-22-74

<u>Work In Process</u>	<u>DATE REQ.</u>	<u>EST. COMP.</u>	<u>DAYS BEHIND</u>
<u>3200 410g</u> Barrel Assembly		7-23	
		7-23	
<u>1100X</u> Fore End Liner		7-22	
		7-24	
		7-23	
		7-22	
		7-22	
<u>700</u> Rear Sight Base		7-22	
<u>WONDER II</u> Trip Components (PARTIAL)		7-26	
<u>552</u> Chamber Tool		7-23	