

PURCHASE ORDER

Les Freer

GUN SHOP

FIREARMS DEALER
LICENSE NO. 74-6344ORDER No. 7476
THIS NO. MUST APPEAR ON
INVOICE, B/L, AND CASES.

DATE

Jan. 28, 1975

2928 SPRING BRANCH DRIVE
HOUSTON, TEXAS 77055
713/467-3016

ISSUED TO

Mr. George Martin
Remington Arms Co.
Ilion, New York # 13357

SHIPPING DATE

VIA

RECEIVED

For prompt payment mail invoice showing order number with bill of lading after shipment is made.
Acknowledge and advise promptly if unable to make immediate shipment.
Goods subject to our inspection, notwithstanding prior payment to obtain cash discount.

FEB 04 1975

QUANTITY	NUMBER	DESCRIPTION
		<p>G. W. MARTIN</p> <p>Dear George:</p> <p>Subject: Trigger malfunctions</p> <p>Re our phone conversations, I am forwarding one Model 700BDL, 25/06, serial #6356761 just as we received it from GLOBE STORE #3, 6200 Bellaire Blvd., Houston.</p> <p>We produced a malfunction in this trigger assembly as follows: cocked the bolt, put the safety on and pulled the trigger - the safety held as it should (did not fire) - then the safety was moved to "fire" position and the trigger pulled again but then the sear failed to trip (did not fire); however a few more pulls on the trigger and it suddenly fired.</p> <p>Like most trigger malfunctions we have found, this one may be difficult to reproduce, may require several attempts to demonstrate but if you keep trying it will occur.</p> <p>Although this particular malfunction is not the same as most recent ones it is closely related to the overall problem. Hope it is of some help to you.</p> <p>SHIPPED UNDER SEPARATE COVER</p> <p>Best regards, Les Freer</p> <p>ON 1-31-75 VIA <u>Paul Post</u> Please acknowledge receipt</p>

RECEIVED
FEB 4 1975
ARMS SERVICE