

## PURCHASE ORDER

*Les Freer*

GUN SHOP

FIREARMS DEALER  
LICENSE NO. 74-6344ORDER NO. 7477  
THIS NO. MUST APPEAR ON  
INVOICE, B/L, AND CASES.

DATE

Jan. 29, 1975

28 SPRING BRANCH DRIVE  
HOUSTON, TEXAS 77055  
713/467-3016

ISSUED TO

Mr. George Martin  
Remington Arms Co.  
Ilion, New York 13357

SHIPPING DATE

VIA

For prompt payment mail invoice showing order number with bill of lading after shipment is made.  
Acknowledge and advise promptly if unable to make immediate shipment.  
Goods subject to our inspection, notwithstanding prior payment to obtain cash discount.

QUANTITY	NUMBER	DESCRIPTION
		<p>Dear George:</p> <p>Subject: M/600 Trigger Malfunctionns</p> <p>Here is another Model 600 trigger problem, serial No.6651698, cal. 6mm, just as we received it from the owner - we have disturbed nothing on the gun, have not even removed it from its stock for inspection.</p> <p>Purchased last Saturday from Carter's Country, Houston, the owner fired half dozen rounds on the rifle range when he had a malfunction by simply failing to get a firing pin fall by pulling the trigger with the safety in normal "fire" position. He then removed his finger from the trigger and the gun discharged as he reached for the bolt handle.</p> <p>The owner assures us that no one has tinkered with any part of the rifle since he purchased it. We failed to produce the same malfunction after several attempts but we find the trigger pull so creepy and rough we have to believe the owner. Here again we find performance of the trigger erratic and frustrating, but very dangerous for this reason. If we were to repair this one we probably would choose to replace the trigger assembly.</p> <p>Hope this helps to point up the problem..</p> <p>Owner: Raymond Osborn 11703 No. Petershan Houston 77071 Ph 498-8312</p>

*Best regards*