

REMINGTON ARMS COMPANY, INC.

Field Service
Bpt., Conn.

RECOMMENDED

GUNSMITH CALL REPORT

CC: Hugh Weavers

in BOYER'S SPORT WEAPONS & GUN SHOP Reporter F. W. Woodrick Date 11 13 71
 Address 201 West Hwy 10 Stevens Point, Wisc. Zip 54481
 Street City State
 Nature of Business Sale & repair Dealer ☒ Large ☒ Small ☐
 Persons Interviewed Mr. Earl Boyer Position Owner & Gunsmith
 Mr. Dan Boyer " "

GENERAL DISCUSSION

The men at this shop reported the usual problems with most of them being corrected without much trouble. This past year have gone thru about 18 to 20 feed latches and today had two M870's 20 Ga with the latches broken, used a dozen fore end supports and a few incidents of inter. latch spring problems. Had a customers M600 rifle in which the complaint was that it fired on closing--Mr. Earl Boyer stated that it was very dirty when received although he could not make it fire without pulling the trigger--to insure it I adjusted more contact with the connector & sear and gave it a good test. Had three 11-48's with functional problems and was able to get two working properly but the third would separate the heads and leave the body in the chamber which needed a factory overhaul. Parts arrive in about three weeks SPECIFIC PROBLEMS after ordering which is considered very good for the others always take several week.