

GUNSMITH CALL REPORT

CC: B B Spencer

Reporter _____

p Name _____ Gunsmith's Name _____

ress _____ Zip _____
 No. & Street _____ City _____ State _____

smith on Premises? _____ If not, give address below:

smith's Address				Zip
No. & Street	City	State		

Recommended List () Open Acct. () % Disc. _____ Dealer () Large () Small ()

PERSONS INTERVIEWED and POSITION:

1. Amesbury, Mass. 1900 (2) _____

_____ (4) _____

SPECIFIC PROBLEMS ENCOUNTERED:

- 1 M 700 25/06 Code LW Shows rust around the front
sight.
1 M 700 25/06 Code LW Stock damaged by the bolt han-
dle--~~a safety inoperative--~~
(Safety bail missing--which I replaced)
1 M870 S197409 V Code JT poor patch in stock & color-
on barrel shows much discoloration & rust.
1 M870 S326363 Code XF coloring coming off barrel &
being spotted.
1 M870 S658532 Code RW Poor polish in bore, (shows
several rough spots half way in the bore)
1 M870 S509795 V Code LW Barrel appears to be dry
& sticky--in wiping it down much discoloration comes
off and coloring is spotted.

(all above barrel: will be returned for correction)

GENERAL PROBLEMS

GENERAL PROBLEMS This Shop reported that a considerable number of feed latches are still showing up along with complaints on burr wood & coloring. Had a #74 that could not be taken down as it need a new port cover & operating handle, did not have a good wrench to remove the barrel take down nut. I was shown several guns with defective bluing & poor patch in the wood work, with finish. I advised that if it was something I would not accept as satisfactory for myself to return it to the factory for replacement. Showed the #3000 a like: that with your thumb around the gun holding it