

GUNSMITH CALL REPORT

30: 3010 111 10100

Date 1. 1. 1971 Reporter P. G. G. G. G.
 Gunsmith's Name P. G. G. G.
10. 6th Street, Minneapolis, Minn. Zip 55403
 No. & Street City State
 On Premises? X If not, give address below:
 Address _____ Zip _____
 No. & Street City State
 Model List () Open Acct. () 30% Disc. _____ Dealer () Large () Small ()
 INTERVIEWED and POSITION:
P. G. G. G., Gunsmith (2) _____
 (4) _____

PROBLEMS ENCOUNTERED:

2 M100 extra barrels that the piston & seal would not go into until smoothed up.

DISCUSSION

Mr. G. G. G. reported this past summer has had two M100 extra barrels that would not properly fit where the rings would go into the gas cylinder until he smoothed the cylinders. Today had a M76 in a box in which an attempted repair had been made on the trigger assembly along with the early style trigger, causing lever which did not have enough clearance for release of the trigger. Also a M740 with a jamming problem which was corrected. During my visit a customer brought in a M700 in which he stated would fire when taken off the safe about once in twenty rounds. This gun was carefully checked out & found nothing wrong--good coverage on the rear & connector--came to the conclusion the customer was evidently holding his finger on the trigger & not realizing it as it could not be made to fire or jar off in any manner tested. The complaint on our good past service for within three weeks the gun was resolved back home--none of the others come close to this service.