

This went to participating gunsmiths

TELEGRAM

Thank you for agreeing to assist us in the installation of a new trigger assembly in Remington 600, Model 660 and Mohawk 600, and XP-100 pistols, covered by our recall.

Our toll free Message Center is advising customers in your area of your availability to make this installation.

We are sending you under separate cover special repair and information forms, plus an initial supply of replacement trigger assemblies.

For your information, Remington will assume full and complete responsibility for any and all claims that may arise out of the design or manufacture of the trigger assembly provided to you by Remington for this modification.

The ^{only} guns included in the recall are all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles, except those with a serial number starting with an "A". Also included in the recall are any XP-100 pistols with a serial number between 0001 and 7,507,983.

If you have any questions, please call Ed Sienkiewicz collect at (315) 894-9961.

REMINGTON ARMS COMPANY, INC.

10/21/73

D.

Person calls in on 800 numbers, asks for Operator 61 or Remington
recall information.

Operator asks for Model No. _____ & Serial Number _____
Checks Model and Serial Number blocks for recalled guns -

if gun is not involved, inform caller
and thank him.

if gun is part of recall, operator will ask for

Name _____
Address _____
Phone Number _____

The operator will say:

"Remington recommends prior to any further usage of your gun
that you bring it directly to a selected gunsmith in your
area for inspection and modification which will be done free
of charge. If you have a pencil and paper handy, the closest
gunsmith is* _____

If you have any further questions you should write to:

Remington Arms Company, Inc.
Box EGL
Bridgeport, Ct. 06602"

*The phone number will be used to determine the nearest Remington
gunsmith (out of 179).

If there is more than one gunsmith in the area, the caller will be
given a name and address. The gunsmiths will be rotated after each
call to assure a balance of customers per gunsmith.

E.

REMINGTON ARMS COMPANY, INC.

Trigger Assembly Special Replacement Program

(A) GUNSMITH

Name _____

Street _____

City, State, Zip _____

Telephone _____
(Area Code)Control No.

--	--	--	--	--	--

(For Rem. Use Only)

GUN OWNER

Name _____

Street _____

City, State, Zip _____

Telephone _____
(Area Code)Control No.

--	--	--	--	--	--

(For Rem. Use Only)

(B) FIREARMS INFORMATION

Model (Check One)

- ☐ 1. Rem 600
☐ 2. Rem 660
☐ 3. Mohawk 600
☐ 4. XP-100

Caliber (Check One)

- ☐ 1. 222 Rem.
☐ 2. 6mm Rem.
☐ 3. 243 Win.
☐ 4. 308 Win.
☐ 5. 6.5mm Rem. Mag.

Caliber (Check One)

- ☐ 6. 350 Rem. Mag.
☐ 7. 35 Rem.
☐ 8. 223 Rem.
☐ 9. 221 Rem. "Fireball"
☐ 10. Rechambered

Serial No.

--	--	--	--	--	--	--	--

(C) MODIFICATION INFORMATION

Method Gun Received From Owner:

(Check One)

- ☐ Hand Delivered
☐ UPS
☐ U.S. Mail
☐ Other _____
(Specify)

Month Day Year

Date Gun Received From Owner

--	--	--	--	--	--

Estimated Completion Date

--	--	--	--	--	--

IMPORTANT — This Copy Must Be Completed and Mailed Immediately Upon Receipt of Gun.

PARTS CONTROL COPY

(completed form to be mailed immediately upon receipt of gun)

We have set up toll free numbers to handle gun owner complaints. These numbers will be in operation beginning Saturday, October 28:

In Connecticut 800-972-9379

Outside Connecticut 800-243-9275

We are doing everything possible to expedite shipment of replacement trigger assemblies; however, the initial supply will be limited. Because these trigger assemblies are the only ones approved for this replacement program, please do not use trigger assemblies you may have in stock.

If you have Model 600 series trigger assemblies in inventory, return them to us freight collect and we will credit your account.

E.