

Nylon 66 Improvements

Problems have been experienced by our stamping vendor in forming the receiver cover to accept the new bolt lock device. Alternative methods are being evaluated.

Two new designs for a barrel mounted scope mount have been completed. One is of stamped construction and the other will be either machined or investment cast. Both designs are being evaluated for cost.