

Asea Manipulator

All polishing equipment for M/742 and M/760 receive polishing is installed.

A new manipulator program ~~for Receiver~~

polishing ~~with the M/742 polishing~~

~~equipment~~ will be

tested in February, 1980. ←

-Dust collector ducts will be altered by February 15, 1980.

Testing of the receiver repositioning system designed

1 to correct misalignment of ^{the} receiver with

the polishing jack contact wheel, was

10% successful. Of 100% success can't be

achieved with the current microswitch