

Monthly Report 479 Seismic Gun.

The percussion fire or closing has been designed and parts as in the NC shop for NC pilot runs. There have been some fundamental changes in the design of the fire or closing.

There were a number of bugs in the guns shipped to MAPCO. These have been solved by MAPCO in the field and they have notified us of this change to debug these guns. Our corrections to these problems have been made in the model drawings and will be tested on the three guns still to be shipped. From ~~with~~ ^{the} ~~the~~ ^{they} then these guns will be debugged fully before ~~shipped~~ ^{they are} shipped.