DESCRIPTION OF CHANGE & REASON: EXTRACTOR MUST BE SHAPED TO BOLT SHROUD BY ADJUSTING BOTH ENDS OF EXTRACTOR ON ALL CALIBERS. CLAW OF EXTRACTOR MUST BE CHECKED ON TENSION PLUG FOR GOT NOGO. add to operation. "assemble tractor to Bolt. M/600 oper 95, mortel 700 oper 95, x provid 788 over 90

COMPONENT STATUS AS AFFECTED BY CHANGE - CHECK TYPE

USE PRI	ESENT PARTS	☐ HOLD FO	R SALVAGE	SCRAP I	PARTS [	REWORK PARTS			
	R50.TM	MENT COST FOR	CHANGE -	PUT ESTIMATED	COST UNDER IT	<u>om</u>			
TOOLS & GA		TING TOOLS		OR EQUIPMENT	PLANT LAYO				
DESCRIPTION OF COST:									

PRODUCT COST - PREPARED BY METHODS & STANDARDS ENGINEER: DATE:								
	REDUCTION IN COST		INCREASE IN CO		IN COST			
ITEM	PRESENT	PROPOSED	ITEM	PRESENT	PROPOSED			
PROD. PORECAST			PROD, FORECAST					
STD, HRS: PER 100			STD. HRS. PER 100					
DOLLARS PER 100			DOLLARS PER 100					
REDUCTION DOLLARS	X		INCREASE DOLLARS	X				
INVESTMENT DOLLARS	x		INVESTMENT DOLLARS	X				
PERCENT RETURN	x		PERCENT LOSS	x				

TOOLING & EQUIPMENT MUST BE AVAILABLE BUFORE PROCESS CHANGE IS INITIATED ATTACH PRESENT PROCESS RECORD PRINTS SHOWING CHANGES INDICATED IN RED RETURN UNACCEPTABLE REQUEST TO ISSUING ENGINEER WITH REASON