

*File Copy*

**REMINGTON ARMS COMPANY, INC.**

INTER-DEPARTMENTAL CORRESPONDENCE



"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" \_\_\_\_\_

Ilion, New York  
September 1, 1978

TO: W. J. BOETTNER

FROM: J. W. BROOKS *JWB*

**XP-100 RECEIVER SIGHT**

We have evaluated the sample Williams sight that you forwarded to us.

When mounted on the front end of the receiver it works satisfactorily with the present front sight.

When mounted on the rear of the receiver the sight bridge and horizontal adjustment knob interfered with the operation of the bolt handle. To alleviate this problem the bolt handle or the sight would have to be changed. A M/700 type handle would clear the sight. With the XP-100 bolt handle the bridge will have to be redesigned or changes made in the sight base and adjustment knob.

In order to mount the sight the receiver had to be drilled and tapped as it is not presently done on our production models. Also, the stock had to be altered to accommodate the sight base.

JWB:T  
Ilion Research Division