

M-600, 660
M-700

GUNS RETURNED WITH CAUSES RELATED TO
TRIGGER ASSEMBLY - CONNECTOR

CAUSE CODE DESCRIPTION	1975		1974		1973		1972		1971		SVR. TOTAL ↓
	600	700	600	700	600	700	600	700	600	700	
3200 - Mutilated	1		1								2
3201 - Broken, cracked	2		2	8	2		4	1	8		27
3202 - Rusty											
3203 - Bent			1	1							2
3204 - Sticky					1	1					2
3205 - Binds on trigger plate or in trigger, or in Rec.											
3206 - Corners rounded at engagement surfaces											
3207 - Soft											
3208 - Chips, etc., under connector							1				1
3209 - Out of pos.				1						1	2
3210 - Connector spring weak, buckled											
3211 - Missing, loose							1				1
3212 - Not adjusted properly (follow down)				1						3	4
3213 - Connector defective			2	2					1	2	7
3214 - Connector guide pin broken, missing, defective											
3215 - Connector spring missing											
3216 - Came loose from trigger											
3217 -											
3218 -											
3219 -											
3220 -											
YEARLY TOTALS	3	0	6	13	0	3	1	6	2	14	48

REQ. F. MARTIN (R+D)
by G BULLIS
6/4/76