

Harvey Bayle

action guns in this model, outside of excessive pressure ammunition, is firing or blowing due to the firing pin sticking forward.

[m/w.o. - Trigger jams forward -

There was a problem some time ago when the seating operation was performed by the first assembler. If too much cement was put on the screw heads, in the process of turning the housing to seat the screws on the opposite side, the excess cement would go between the side plates in the area of the rear spring. The procedure now is for this operation to be done by a sub-assembler who leaves the housing in one position until the cement dries. Then the housings are turned over, and the opposite screw cemented.

Joe Bauer
12/29/75