

A669980

Dent in stock left side near rec. right screw.
 Bar string stuck in too far cracking wood.
 Bolt finish not compatible.
 Barrel contacts stock right side
 Brass reinforcing pin protruding

A6699811

Bolt finish not compatible
 Brass reinforcing pin protruding.
 Dent in barrel over chamber.
 Checkering over-run. - border does not clean up.
 (fore-end panels).

A6699841

Bolt finish not compatible
 Poor fill at reinforcing screw.
 Mass on barrel from gun trucks.
 Scratches on barrel.

A6699689 - ~~689~~

Bolt finish not compatible.

A6699023

Bolt finish not compatible
 Brass reinforcing screw protrudes.
 Checkering over-run. Barrel did not clean-up
 (fore-end). Dent in stock Mass on toe of stock
 from gun trucks
 No pressure on bolt rod.

(2)

A6699882

Poor cut at pod. Uneven.
Bolt finish not comparable.
Finish marks in stock
Excess finish at rear of eye. port on stock.
Rear sling screw too deep. wood chipped.

A6699871

Bolt finish not comparable
Dent left hand side of stock
Excess finish along left side of stock.
Bolt release latch binds.
Dent in right side of trigger housing caused by
screw driver

A 6699853

Bolt finish not comparable.
Off center sanding at fore-end tip.
Checkering over-run. Guard does not clean up