Remington. - OFFID REMINGTON ARMS COMPANY, INC. . PUBLIC RELATIONS . BRIDGEPORT, CONNECTICUT OGGOZ

RELEASE

FOR RELEASE INMEDIATELY

Company, Inc., announced today that under certain unusual circumstances on some of its center fire bolt action firearms, the safety selector and trigger could be manipulated in such a way that subsequently moving the selector to the fire position could result in accidental discharge. Remington firearms involved are Model 600, 660 and Mohawk 600 rifles and XP-100 pistols manufactured prior to February 1975.

The difficulty can be corrected by installation of a new trigger assembly. In view of the potential safety hazard, the Company is recalling all of these guns produced prior to February 1975 for inspection and modification as required.

Efforts are being made to contact owners of these guns.

Individuals who have Model 600, 660 and Mohawk 600 rifles or

XP-100 pistols involved in the recall should write to Remington rms Company, Inc., Bridgeport, CT 06602, or call the following tol? free number for information on procedures:

In all states except Georgia:

800-241-8444 - Ask for Operator 61

In Georgia:

800-282-1333 - Ask for Operator 61

- MORE -

- A. General Press Release
- B. Financial Press Release
- C. Telephone Request to Gunsmiths
- D. Telegram Confirming Gunsmith Participation
- E. Format for Atlanta Information Center
- F. Gunsmith Receipt and Repair Form
- G. Telegram Informing Gunsmiths about Customer Complaint Numbers
- H. Sales Data For 600 Series Rifles
- I. Serial Number Clarification