

1-21-79

R.K.

[illegible]

1-31-79

XP 100 TEST - ENDURANCE MEASUREMENT SUMMARY
2-CONTROL SAMPLES / 2-ALTERED SAMPLES / 2-PRINT SAMPLES

Measurements	0 lbs	500 lbs	1000 lbs	1500 lbs	2000 lbs	2500 lbs	R.K.
C-1 B-7504938							
TRIGGER Pull-Avg of 3	2.0	2.0	2.0	2.0	2.0	2.0	
SAFE ON/OFF (ON)	2.0	2.0	2.0	2.0	2.0	2.0	
FORCE-Avg of 3 (OFF)	2.0	2.0	2.0	2.0	2.0	2.0	
SEAR LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
FORWARD NULL LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
C-2 B-7506393							
TRIGGER Pull-Avg of 3	2.0	2.0	2.0	2.0	2.0	2.0	
SAFE ON/OFF (ON)	2.0	2.0	2.0	2.0	2.0	2.0	
FORCE-Avg of 3 (OFF)	2.0	2.0	2.0	2.0	2.0	2.0	
SEAR LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
FORWARD NULL LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
A-2 B-7506187							
TRIGGER Pull-Avg of 3	2.0	2.0	2.0	2.0	2.0	2.0	
SAFE ON/OFF (ON)	2.0	2.0	2.0	2.0	2.0	2.0	
FORCE-Avg of 3 (OFF)	2.0	2.0	2.0	2.0	2.0	2.0	
SEAR LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
FORWARD NULL LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
A-3 B-7506234							
TRIGGER Pull-Avg of 3	2.0	2.0	2.0	2.0	2.0	2.0	
SAFE ON/OFF (ON)	2.0	2.0	2.0	2.0	2.0	2.0	
FORCE-Avg of 3 (OFF)	2.0	2.0	2.0	2.0	2.0	2.0	
SEAR LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
FORWARD NULL LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
P-2 B-7506257							
TRIGGER Pull-Avg of 3	2.0	2.0	2.0	2.0	2.0	2.0	
SAFE ON/OFF (ON)	2.0	2.0	2.0	2.0	2.0	2.0	
FORCE-Avg of 3 (OFF)	2.0	2.0	2.0	2.0	2.0	2.0	
SEAR LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
FORWARD NULL LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
P-1							
TRIGGER Pull-Avg of 3	2.0	2.0	2.0	2.0	2.0	2.0	
SAFE ON/OFF (ON)	2.0	2.0	2.0	2.0	2.0	2.0	
FORCE-Avg of 3 (OFF)	2.0	2.0	2.0	2.0	2.0	2.0	
SEAR LIFT	2.0	2.0	2.0	2.0	2.0	2.0	
FORWARD NULL LIFT	2.0	2.0	2.0	2.0	2.0	2.0	

