

M1700 BDL 7x57-Press Stock - Evaluation

10-24-79
C.J. Sweet

#6053

- Poor fit of butt plate - gaps between plate and wood - toe overhangs.
- Checkering on fore arm - bumps - feels warped
- Stock is dinged at grip -
- Rear stock screw held by approx 1 thread
- Magazine box cut too deep - box moves up & down .100"
- Wood chipped out near floor plate cut.

#6222

- Butt Plate missfit all around.
- Discoloration around checkering at grip
- Bubbling of finish where bolt handle locks in.
- Rear stock screw held by 1 or 2 threads
- Magazine box cut too deep

#6132

- Poor fit on butt plate
- Warping effect in forearm checkering
- Stock cracked on left side at checkering
- Cone of stock marked up
- Hard to read the "F" & "S" at safety selector
- Rear stock screw grabbing by 1 or 2 threads
- Mag box cut too deep

6175

- Checkering on forearm bottom - peaks uneven & shallow.
- Pits in finish
- Dark spots in checkering
- marking at comb
- Wood chipped out at checkering & cracking on left side at grip.
- Mag. box cut to deep
- Rear stock screw held by about 2 threads
- "F" & "S" Stamp very light
- Poor finish on trigger guard
- Poor fit on butt plate

2659

- No sling strap screw holes
- Stock reinforcing screw - stain sanded away
- Open grain on stock
- Butt plate poor fit
- Chip out of bolt plug
- Rear stock screw held by 1 thread
- Mag box cut to deep

#5755

- 1.750" ridge at pistol grip front
- Excessive finish at roof receiver on stock.
- Butt Plate fit poor
- Rear Stock Screw held by 1 or 2 threads
- Mag box cut too deep

#5254

- Uneven checkering on right side of grip.
- "F" & "S" Stamp at safety selector not deep enough
- Some areas have open grain
- Safety lever cracked
- Mag box cut too deep.

6173

- Ridge on front of grip
- Big gap between Butt Plate & Stock
- Open grain on right side of forearm
- Markings around cone
- Rear receiver screw held by 1 thread.
- Mag box cut too deep.