

REMINGTON ARMS COMPANY, INC.

INTERDEPARTMENTAL CORRESPONDENCE

Remington
CHURCH

PETERS
CHURCH

J. R. Snedaker
S. A. Fanelli
File

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____

December 1, 1980

TO: J. H. Hennings *01 12-3-80*

FROM: A. J. Long *12-3-80*

SUBJECT: M/700 Safety Lever with View Hole
M/700 Sears - New Chrome Plate Process

Date Started: 9-29-80

Date Finished: 10-7-80

Work Order: C-1803

Introduction:

Received from Design five (5) M/700 Fire Controls for dry cycle. These samples have a new view hole in the safety lever and also chrome plated sears.

Test Objective:

~~To evaluate the new chrome plating process on the sears for cracking or peeling.~~ Test to include the evaluation of the new chrome plating process on the sears for cracking or peeling.

Test Observation:

All samples were tested a total of 20,000 cycles each without any breakages or wearing of chrome occurring.

Test Procedure:

All samples were run in a M/700 safe on/off dry cycle machine with a cycle rate of one every second.

Test Procedure (continued)

Inspection cycle and measurements were taken every 2,500 cycles.

Sample	Sear Lift with Safe On	Sear Lift Fwd. Null	Safe On	Safe Off	Trigger Pull
1 - 0 Cycles	.011	.0055	7.15	8.40	6.45
20,000 Cycles	.0105	.006	5.05	5.05	6.10
2 - 0 Cycles	.008	.0035	6.70	6.00	5.90
20,000 Cycles	.0075	.002	4.05	3.75	6.35
3 - 0 Cycles	.009	.0045	8.90	6.90	5.90
20,000 Cycles	.0095	.0045	5.55	6.35	6.30
4 - 0 Cycles	.008	.003	7.10	8.85	5.35
20,000 Cycles	.0075	.003	3.60	3.70	5.45
5 - 0 Cycles	.008	.0035	5.55	6.30	6.05
20,000 Cycles	.008	.003	5.50	4.75	5.75

Future Work:

Additional testing should be conducted on Pilot Lot if accepted.

AJL:ws