

To Paul Holmberg

Ref item 5 on p2 - John Hyde  
have heard this one before <sup>John Hyde wife believed your look for this</sup>

<sup>File</sup>  
<sup>m/700</sup>  
~~from~~ this up pressure is caused by  
~~the~~ a ring of wood left inside the  
forend channel. John Hyde would

like this ring moved forward to the  
end of the forend to eliminate current  
gap between barrel and end of forend -  
needs R+D to say O.K. Maybe  
you can apply some 'up' pressure from  
your end and we can combine these  
two.

① ~~to the~~ I've got no objection  
② TWR from T.W. LAWSON  
also haven't heard this!  
M700 don't shoot!  
Paul

ROUTE TO: J. P. McAndrews  
~~E. F. Barrett~~  
~~J. G. Williams~~  
~~E. Heston, Jr.~~  
~~F. T. Millener~~

TWR