

VISUAL INSPECTION

A-16

Machining Marks
and Poor Color to
all Bolt Heads.



Clean Break Line
Between Jewel
and Color.



Lack of stain
under RKW
Finish.

