		rent		New	t.	Vendor Tooling Plant Tooling Machine Investment	Commonts
	And	14)('		AD1.	18D1.		
Base: Current M700 ADL	\$158.50	\$158.68	\$158.68	\$158.48	\$158.68	•	
Stock Features							
Current BOL Stock Assembly		13.81			13.81	110,000	3 machines + tooling
"Classic" Style Stock			(2.30)	(2.30)	-		
Birch Stock Blank			(14.04)				
M788 Lacquer Finish			(6.11)				
High Solids Finish				(2.56)	(2.56)		
Cut Checkering		(1)		7.23	(1)		
M788 Butt Plato			(.34)	•			
M/Four Butt Plate				(,34)			
M700 BOL Grip Cap		(1)		. 56	(1)		Included in Stock Assembly
M/Four Grip Cap					(.61)		
Contrasting Wood Fore End Tu	D:				No		Included in Stock
White Line Spacers		(1)			(1)		
Sling Swivel Stude		(1)		1.18	(1)		•
Sling Strap & Swivels		5,49					
Sight Features	•					•	
Front Sight Hood		.89					
M788 Sights			(3,41)	~		•	
Delete Sights (3)				(6.05)	(6.05)		
Scope Mount (4)						360,000	3 machines + tooling
Trioger Guard Features				• ••			
Hinged Floor Plate (Alum.)		4.82		4.82	4.82		
Stamped Trigger Guard			(2.07)			Unknown	
Hinged Floor Plate (Steel)							
Bolt Features	•						
Delete Bolt Lock			Nil	Mil	Nil		
Delete Bolt Jeweling			(.44}				
Magazine Follower	•						
Stamped Follower			(*3.55)	⁽²⁾ (3.55)			
Redesigned Cast Follower (2)					Nil	10,000	
Jeweled Follower	-				.44	. Unknown	
Improved Metal Finish				1.94-	1.94	10,000	
Added Assembly Costs.		1.03		.51	1.03		
Sub Total	\$15 8.69 4	\$184.72	\$124.93	\$160.LZ	\$172.72		
Less: Effect of Incressed Volu		•	(2.61)	(3.37)	\$ 3.72)		
Factory Cost	\$158.68	\$184.72	\$122.32	\$156.75	\$169.00°5	•	
				=			

10-15-61

⁽¹⁾ Included in BBL Stock Assembly
(2) Machined follower under study - could cut cost by 50% - needs 300,000 investment
(3) See (4)
(4) Optional - 7.70 to 12.00 per gum - get into business - all rifles, not just 700
(5) Sight option must be edded