

VISUAL INSPECTIONS

The Strands had
to be cut off.



Gap between
Recoil pads
and stocks.



Some large
knots on the
stocks.

