


VIII. • Remington M-700 Continued

Fig. No. 6



• Ruger M-77

There were no adjustments made on the Rugers.

The only remarks were: "It's very easy to load the magazine. . . and "The bolt operates smoothly".
(Shooters' quotes)

• Smith & Wesson M-1500

There were some problems with live-unload. The rifles would extract the cartridge, but they would not eject them all the time.

• Winchester M-70XTR

Some action binds; had to lubricate the bolts the same as the Remington M-700s.