

Machining Marks
and Poor Color
to all Bolt
Heads.



Clear Breakline
Between Jewel
and Color.



Lack of Stain
Under RKW
Finish.

