

→ John Lunde ~~C. P. Campbell~~
 Should these have been provided
 as a routine part of new model
 production?
 Scott Jensen

xc: J.P. Linde P.C. Earl
 W.S. Johnson K.R. Thondukolam
 M.J. Kantor D.J. Anderson

DON'T SAY IT-WRITE IT

To P.G. Johnson

Date December 29, 1982

From J.A. Harter

M/7, M/700 RESTYLE & M/4 L.E. RACKS
NEEDED FOR BLACK OXIDE

We need drawings and racks made for the following components to meet production schedules and quality standards through the Black Oxide Process. I understand there are funds available (see D.J. Anderson). These should be expedited:

M/7 - Trigger Guards	M/700 Restyle - Bolt Assembly
Bolt Assembly	Bolt Plugs
Bolt Plugs	Rear Sight Base
Floor Plate Base Assembly	
Floor Plate Cover Assembly	M/4 L.E. - Trigger Guards
Floor Plate Pads	Rear Sight Base
Rear Sight Base	

JAH:cap

"DON'T TAKE A CHANCE, THINK SAFETY IN ADVANCE"

→ Scott

Racks should have been provided for some of these parts - not for others -

We are presently evaluating our treatment of coloring racks and other protection aids for new products. However, the Bolt Assemblies, Bolt Plug & Rear Sight Bases are Add-Used Components for which presently existing racks can be used. In those cases, we would ~~not~~ only provide racks for significant increases in volume.

Gay Campbell
 1-10-83