

REMINGTON GUN REPAIR SURVEY
REMINGTON GUN REPAIR TALLY FORM

SHOP NAME GUNATORIUMGUNSMITH Mike SullivanADDRESS 5323 N ARGONNE SPOKANE WA. 99206

DATE	MODEL	SERIAL NO.	REPAIR MADE
7/5/82	700	B6244847	SALTS IN EJECTOR
10/9/82	760	D7172875	Weak action Bar lock spring
10/21/82	700	A6882587 ^{4A}	STOCK CRACKED
1/6/83	700	B6224986 ^{PA}	? STOCK CRACKED
1/11/83	760	D7233835 ^{OL}	Lubed grease in fire pin
1/25/83	1100 LT20	N560707K ^{AB}	Broken action Bar spring
3/18/83	820	V329361V ^{KO}	Broken stock
3/21/83	700 BDL	A6663337 ^{EO}	" "
3/30/83	700 BDL	B6368217 ^{AS}	Misfire Check Test fire
4/11/83	7	7601744 ^{BD}	Triggers (updating)
4/22/83	7	7604686 ^{SA}	TRIGGER (updating)
7/14/83	870	V620249M ^{SB}	shell latch R.H.
8/15/83	700	6517709 ^{AB}	fire solenoid released
8/18/83	700	A6 B6236520 ³	" "
8/17/83	870	V11637X ^{RO}	LH shell latch Broken
8/22/83	9200	OV47199 ^{BO}	ADJUST TRIGGER SCREW
9/7/83	870	V552862M	ejector come off
9/15/83	870	V798422M ^{XB}	STOCK CRACKED
9/10/83	870	V943699V ^{PD}	Block pin, fell out (Locking)
11/14/83	74	A4042406 ^{SA}	Work done on shell mechanism
11/15/83	742	A7305694X1	Ejector defective
11/16/83	1100 LT20	N627571K	BURR IN CHAMBER