

I

4/14/83

4-11-83

Firearms Product Manager
Remington Arms Co, Inc.
939 Barnum Ave.
Bridgeport, Conn. 06602

J. A. S. Simon
Please handle

Thurman

RECEIVED

APR 11 8 10 AM '83

J. A. S. Simon

Dear Sir:

I purchased a 788 Remington rifle in
.243 caliber on 1-12-82, serial No.
B6096449.

I am satisfied with its accuracy, but
the safety seems sloppy. It slips to
the firing position very easily, sometimes
even accidentally. The biggest trouble is
the cartridges hit the scope on ejection
and fall back into the chamber.

I have had it to the gun smith
school twice at the VoTech in Pine
City, Minn. They put higher scope
mounts on it and checked it all over
for burrs and etc. They still hit
the scope. I have talked to several
people with 788's and they all have
the same problem.

/

II

I know it is a low priced rifle, but it should work. Especially, with a name like Remington, I expected quality. I tried to trade it for a higher priced rifle and the dealers all know about the problems and do not want any used 788.

Is there any fix to this rifle, or should I throw it away and buy a different brand.

Sincerely,
David Mason

Route 1

Hinckley, Minn. 55037

David Maser
Route 1, Minn.
Hickley, 55037



1
Firearms Product Manager
Remington Arms Company, Inc.
939 Barnum Avenue
Bridgeport, Connecticut
06602