SEQUENCE	OF	PEI	RATIONS
		OP. I	

OP. No.	OPERATION		OP. No.	OPERATION	DEPT.
	•		80	Assemble Front Sight Base to Barrel with Front Sight Base Screws.	61
20	Assemble Rear Sight Assembly.	61			
30	Remove burr from Ejector hole at face of Bolt.	61		· .	
40	Fit and head Bolt Assembly to Barrel Assembly.	61			
50	Fit and head Bolt Assembly to Barrel Assembly (GMM)	61			
65	Make chamber cast.	61			
70	Ream Ejector hole.	61			·
DATES	AND REASONS FOR REVISIONS		DATE	S AND REASONS FOR REVISIONS	
3/4/78 - Retyped & filed with process no. 276772			10/3	31/78 - Rev. and re-numbered Op. 5-18. WW	
	78 - Chg. dept. 41 to 61 - Hardy - 276772 .78 - Obs. op. 16 - combined with op. 15 - MH-2769	020	7/7/	83- Obs. Op. 17 & chg. page # - RLS - 283006	
MODE			L	PAGE . 1 OF 4	
	GA. OR CAL.				
	PART No.				
		ـــــــــــــــــــــــــــــــــــ			