

Rev. 2-15-61

P.I. No GUN EXAMINATION REPORT NUMBER: 50 MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 29532
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-8-82
FIRED AMMO TYPE: UNKNOWN FROM: GEORGE P. INC.
9615 100th Ave. S.W.
BECKMAN, AL. 36006
& CONDITION: — GUN #: B6330831
PROOF: REP. INSP.: 115 TEST: 118 CODE: 5-81
HEADING: O.K. GA./CAL.: .30-06 SPRG.
BREECH OPENING: O.K. CHECKED BY: JSW
RECOIL SHOULDERS: O.K. APPROVED: JSW 11/11/83
CHAMBER: O.K. APPROVED: JSW 11/11/83
TEST: — APPROVED: B.V. 11/11/83
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: —
NEW

COMPLAINT: "... WHEN YOU PULL THE BOSS UP TO UNLOAD THE GUN,
THE SHELLS FIRE."

INCIDENT: —

COMMENTS: Gun fails track test, fire control appears to
full of crud impeding proper function of trigger
& other fire control parts. Front adjusting screws
have sealant removed.

Trigger pull 5 1/2 #

Sealant .0105 - mill .0055

Replace fire control - No change JSW