

DON'T SAY IT—WRITE IT

To Jim Stahl
From Paul Jackson

Date 3-26-84

M/700 BDL 30-06 [MANUFACTURE DATE 9/69]

SERIAL # 6280288

SEAR-CONNECTOR ENGAGEMENT = 0.007"
SEAR LIFT (NULL POSITION) = 0.0035"

Trig. pull O.K.

Followed down on 10 consecutive attempts at -40°F.

First dry fire at room temp very sluggish

Molasses-like substance caused seal to stick in housing.

"YOUR SAFETY ATTENTION MEANS ACCIDENT PREVENTION"