

MONTHLY REPORT

William A. Warren Jr
1-19-88

SAFETY

- COMPLETED "REQUEST FOR SPECIAL LOCK-OUT AND TRY VARIATIONS" FOR NEW SAFETY PAINT MACHINE NOW CIRCULATING FOR COMMENT/ APPROVAL.
- IT WAS AT OUR DEPT. SAFETY MEETING WHERE THE SUGGESTION WAS MADE TO PUBLICIZE WHAT A BROWN RECLUSE SPIDER LOOKS LIKE - DONE AS FOLLOWUP TO EMPLOYEE O. T. J. LAST TIME INJURY.

SIGNIFICANT PRODUCTION SUPPORT PROBLEMS

- COMMON SEAR BUTT MILL OPERATION. LOCATOR WAS MARKING PART FAILED PREMATURELY AND WAS UNIQUE TO THIS MACHINE. PROBLEM IDENTIFIED & CORRECTED WORKING WITH OPERATOR AND TOOLMAKER. TDR WRITTEN.
- 552 NONCONFORMING BOLTS WERE ACCEPTED OK THRU MACHINE LOCATORS BUT GAVE FALSE READING ON SEVERAL GAUGES. IDENTIFIED PROBLEM AND SOLUTION TO FOREMAN AND OPERATOR.

NEW MACHINE

SAFETY PAINT MACHINE FIRST RUN 12.31.87.
FIRST GOOD PARTS ON 1.5.88
AS INSPECTION COMPLETED ON 1.13.88
AND ACCEPTED BY PRODUCTION.
THERE IS STILL WORK TO DO ON S.O.P.'S
REDESIGN OF MACHINE ELEMENTS,
IMPROVING YIELD AND RESOLVING
ISSUE OF ADDITIONAL PAYMENTS REQUESTED
BY VENDOR. I WILL BE INVOLVED ~~HERE~~
HERE FOR AWHILE.

SPECIAL ITEMS

TARP: ASSISTED WITH DEVELOPING PROCESS
ALTERNATIVES AND WRITING PROCESS
FOR TR ASS'TS TO BE SENT OUT AND
GUNS TO BE REWORKED IN HOUSE.

REVIEWED AND COMMENTED ON INFOR-
MATION TO BE SENT TO GUNSMITHS
FOR VALIDITY AND CONSISTENCY.

- PARTICIPATED IN DISCUSSION AND COMMENT ON TOPIC: "WHAT DO PROCESS ENGINEERS DO?"
- COMPUTER LISTING ON RESULTS OF WAREHOUSE SURVEY FOR HARD TRIGGER PLATES (ZINC) COMPLETED BY BUS. SERV.