

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

Dear Remington Dealer:

Our records show that you are the holder of one or more Model XP-100 pistols in need of possible trigger assembly correction. The serial number(s) of the concerned pistol(s) is listed on the enclosed form.

As delivered to you from the factory, your Model XP-100 met all Remington tests and inspections that have set the industry quality standard for this type of sporting arm.

However, during routine servicing of this model, Remington discovered that an incomplete factory operation, involving the front trigger housing screw, may have introduced the possibility of an unsafe trigger assembly condition in a limited number of guns. Although unlikely, with normal usage of the pistol, the front trigger housing screw may position itself in such a manner as to promote firing upon release of the safety or upon bolt closing.

Since the safety and quality of our firearms is our utmost concern, Remington will, at no charge, correct the affected trigger assembly part in all pistols which could possibly be involved.

Therefore, we request that you ship your pistol(s), via United Parcel Service, Transportation C.O.D., to:

Remington Arms Co., Inc.
Dept XP
14 Hoefler Ave.
Ilion, NY 13357


Since we are aware that many customers have custom stocked their pistols, we ask that these customers remove the barreled action from the custom stock and send the barreled action only. However, those customers having pistols containing the factory installed Zytel stock may ship the complete firearm in its original factory stock.

-3-

If you have any questions about this trigger assembly correction program, please call toll free at the following 800 number:

In U.S.A. - (800) 634-2459
In Canada - (800) 634-5401
(8:00 a.m. - 4:30 p.m. EST)

Sincerely,



R.H. Potter
Product Service
Specialist

RHP:auc
Encl.

R2518316