

XP100 DRY CYCLE

CYCLES X 100	SEAR ENGAGEMENT		
	CONT 6604	EXP 5583	DEF 6172
0	0.0193	0.022	0.0191
5	0.0169	0.0211	0.0217
10	0.0203	0.0208	0.0209
15	0.018	0.0215	0.0222
20	0.0212	0.0173	0.0234
25	0.0229	0.0243	0.0239
30	0.0222	0.0239	0.022
40	0.022	0.0239	0.0167
50	0.0227	0.025	0.0229
60	0.0225	0.025	0.022
70	0.0218	0.0263	0.0224
80	0.0233	0.0278	0.0221
90	0.0232	0.0265	0.0239
100	0.0235	0.0292	0.0239