NAME: Willam C Gilly DATE: 12-1-39
ADDRESS: 402 West Houston Pursaline 127300
PHONE NO.: НОМЕ: <u>Ч\5- \87 \</u> WORK:
TYPE OF RIFLE: Pening for CALIBER: 30-CL SERIAL NO.: A-6419765
DATE OF MANUFACTURE OR TWO LETTER DATE CODE STAMPED ON BARREL, LEFT SIDE JUST ABOVE STOCK NEAR THE RECEIVER:
DATES THE GUN WAS PURCHASED AND ACQUIRED BY YOU IF DIFFERENT:
who purchased the gun: Me
WHERE WAS THE GUN PURCHASED: Country - 1-10 West
DO YOU STILL HAVE THE INSTRUCTIONS THAT CAME WITH THE GUN?
PLEASE GIVE A BRIEF DESCRIPTION OF WHAT YOU WERE DOING IMMEDIATELY BEFORE AND AT THE TIME THE GUN DISCHARGED WITHOUT YOU PULLING THE TRIGGER: Cotting roody To un loved after a hunt. I moved The Safety Lich was off To off and the Rith find - curat Through a wood well back of my Rick us campe through the
DATE THIS INCIDENT OCCURRED: Nov 1978
PLACE THE INCIDENT OCCURRED: Wadisonille Toxas
AT THE TIME OF DISCHARGE WERE YOU (MORE THAN ONE ANSWER MAY APPLY):
(1) IN THE PROCESS OF LOADING OR UNLOADING THE GUN YESNO
(2) RELEASING THE SAFETY
(3) OPENING THE BOLT YESNO
(4) CLOSING THE BOLTYESNO
WHAT WAS THE TEMPERATURE AT THE TIME THE GUN DISCHARGED? A opro 40°
WHERE AND UNDER WHAT CONDITIONS WAS THE GUN STORED DURING THE PREVIOUS 24 HRS? 1 な な かっさんと じょうい
WERE THERE ANY WITNESSES TO THE ACCIDENT? IF SO, PLEASE STATE THEIR NAME, ADDRESS AND TELEPHONE NUMBERS:
30Kg
Convoe Tix Too order by Sin
Convoe Tix Isachalis variation and DID ANYONE SUFFER AN INJURY? (IF Sp. State of New York Count of Westchester, Index No. 9344/001
Vestchester, John Court of
No. 9341/2 of

WAS THERE ANY PROPERTY DAMAGE? (IF SO, PLEASE EXPLAIN). HCK-un (amage - Back window of Pick-up - fund collidation)
HAS ANY TYPE OF LAWSUIT BEEN FILED? IF SO, PLEASE PROVIDE US WITH THE NAME, ADDRESS AND TELEPHONE NUMBER OF ALL ATTORNEYS INVOLVED.
No
HAS THE RIFLE ACCIDENTALLY DISCHARGED MORE THAN ONE TIME?
IF SO, GIVE SPECIFICS FOR EACH TIME:
HAVE YOU NOTIFIED REMINGTON OF THESE OCCURRENCES OR RETURNED THE RIFLE TO REMINGTON?
DO YOU STILL HAVE THE RIFLE? Ves
HAVE THERE EVER BEEN ANY ADJUSTMENTS TO THE RIFLE'S FIRE CONTROL SYSTEM SUCH AS THE TRIGGER PULL, TRIGGER OVER TRAVEL, OR TRIGGER ENGAGEMENT? PLEASE EXPLAIN ANY ADJUSTMENTS. I Sent The Gun To Pangueton they checked the Whole Bolt & Pring mechinecis
it - said they toolseed the whole Bolt & firing mechinicis
HAS IT EVER BEEN SENT TO A GUNSMITH OR ANYONE ELSE FOR REPAIRS? IF SO, PLEASE LIST THE NAME, ADDRESS AND TELEPHONE NUMBER OF ANY PERSON WHO REPAIRED THE RIFLE. ARE THERE ANY BROKEN PARTS ON THE RIFLE, IN PARTICULAR THE TRIGGER CONNECTOR? IF SO, WHAT PARTS WERE BROKEN?
N ₀
HAS THE RIFLE DEEN WELL CARED FOR, REGULARLY CLEANED AND LUBRICATED? PLEASE DESCRIBE THE PROCEDURES FOLLOWED AND MATERIALS USED.
APPROXIMATE NUMBER OF ROUNDS FIRED PER YEAR (BOTH BEFORE AND AFTER THE ACCIDENTAL DISCHARGES): 12 ferc - None - After Maybe 10 over 21
WHAT IS THE GENERAL CONDITION OF THE RIFLE?
OF YOU KNOW ANYONE ELSE WHO HAS HAD A TOPHINGTON MODEL 700 OR MODEL 600 RIFLE HAT HAS DISCHARGED WITHOUT THE TRIGGER BETWOPPILED? IF YES, PLEASE PROVIDE US WITH THEIR NAME AND RESEARCH IN THE PHONE NUMBER. INC. Supreme Co. New York Co. N
IF YES, PLEASE PROVIDE US WITH THEIR NAME CANDIDERS TO THE PHONE NUMBER.
the State of New York, Court of
Thesicnester, Inc. York Court of
the No. Remington Arms. Westchester, Index No. 9344/95"