

BARBER - Kinzer PPS GAL RE0000006

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
94-14520

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED DATE OPENED DATE CODE

04/28/94 04/28/94

SERIAL NUMBER

A6471639

NEW SERIAL NUMBER

MODEL AND GRADE

700 BMM MAG BDL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

AAA ACE BUYERS
823 B HWY. 99N
EUGENE

OR 97402

AAA ACE BUYERS
823 B HWY. 99N
EUGENE

OR
97402

CUST NO: 096689 C.O.D.

ACCOUNT NUMBER

063103

ACCOUNT NUMBER N/C

WRITE

☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Expedite per C. Mocko

REPAIR CHARGE

20.

EXCISE

TAX

INSURANCE

UPS

8.0

PARCEL POST

TOTAL

28.

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	<i>Safety is defective sometimes it fires</i>				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Front pull and trigger guard screw has been adjusted outside of the factory. Remington does not recommend that the trigger adjusting screw be adjusted outside of the factory. Exchange trigger assy at a spray price strictly as a gesture of good will and to restore customers confidence in AR15. FRONT GUARD SCREW does not tighten properly exchange NA.

PARTS

Front guard screw

COMMENTS

*Trigger pull measured 2 LB's
Rec'd and sent left was .010.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PAT
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 RE

BARBER - Kinzer PPS GAL RE0000006

PPS 00001