

RECEIVING AND ESTIMATING REPORT

CUST NO: 051909 C.O.D		COMMENTS NO CORR	
CUSTOMER ORDER NO.			
DATE RECEIVED 0/24/91	DATE OPENED 10/29/91	DATE CODE 0A 7-80	SERIAL NUMBER B6244946
ACCESSORIES W/STUDS		MODEL AND GRADE 700 30-06 BDL	
		ORDER R 91-21777	
SOFT CASE			

FROM:

ADAMS, JOHN
1229 EAST 87TH ST
BROOKLYN
USA NY 11236

SHIP TO:

ADAMS, JOHN
1229 EAST 87TH ST
BROOKLYN
USA NY 11236

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11-4-91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	----------------------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

NO correspondence. "Pull trigger, would not fire; changing position of gun causes it to fire".

GUN FAULT

Could not duplicate above complaint. However, disassembly of rifle revealed trigger assembly extremely dirty and contaminated with gumming residue. Trigger inner parts not moving freely - near safety catch sticking on trigger assembly with later improper maintenance. Trigger pull 5 1/2 pounds; rear left cog 30° Bolt stop gummed-up; not operating properly.

Clean present trigger assembly if possible. If not, offer replacement trigger at 1/2 normal cost as a gesture of good-will.

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4925 REV. 7/90