

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

December 28, 1988

Ahlman's  
Route 1, Box 20  
Morristown, MN 55052

Gentlemen:

Examination has been completed on the Model 700 280 Rem caliber Mountain Rifle, serial number B6858761, that you returned to us because "customer stated that gun went off when safety was moved from safe to fire".

The returned firearm, which was produced in April of 1987, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be very good. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the condition that was reported. Factory seals were intact on the trigger adjustment screws, indicating that no adjustment had been made to the trigger outside our factory. Trigger pull was measured to be 5 1/2 pounds, and sear lift with the safety in the "on-safe" position was well within our specifications at .012". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.