



13078

TO: Rem.

This firearm has the following defect: Gun fires
by itself

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052

RETURN POSTAGE GUARANTEED