

15/58  
Dennis  
VERIFIED T.P. 2# / S.L. .0095  
TRIGG. ASSY HAS BEEN TAMPERED WITH  
ADJUSTED OUTSIDE OF FACTORY - IS  
GUMMY - SLUGGISH TRIGGER MECHANISM.  
EXPLAIN TO CUSTOMER AND OFFER  
1/2 PRICE REPLACEMENT

Martin