

RECEIVING AND ESTIMATING REPORT

CUST NO: 005292 ILION		COMMENTS W/1 SWIVEL		STEYK	
INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 10/18/91	DATE OPENED 10/22/91	DATE CODE DY 7-74	SERIAL NUMBER 6765646	MODEL AND GRADE 700 7MM MAG ADL	ORDER R 91-212
ACCESSORIES			L/SIGHTS		
FROM: ALLISON & CAREY GUN WORKS 10218 S. E. POWELL BLVD. PORTLAND OR 97266			SHIP TO: ALLISON & CAREY GUN WORKS 10218 S. E. POWELL BLVD. PORTLAND OR 97266		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE 10/28/91	VIA UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST "Customer says rifle fired twice when taken off safety"

MAIN FAULT (cannot duplicate above complaint. However, it was noted that the trigger assembly has been adjusted outside of factory and is outside our specifications 1) trigger pull measured at 2 1/2 pounds (trigger does not have positive indication) 2) over-travel is excessive. Also, it was noted that trigger assembly is extremely dirty and dirty. Ser-lyt "007"

REPAIRS Clean trigger assembly (if possible) and re-adjust to factory specs. 21, Offer new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN AAR	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4925 REV