

RECEIVING AND ESTIMATING REPORT

COMMENTS
ATTN JIM STERL

INITIALS
EJB

CUSTOMER ORDER NO.
09724/90

DATE OPENED
09/26/90

DATE CODE
OR 7-68

SERIAL NUMBER
120272

MODEL AND GRADE
660 6.5 MM LS

ORDER NO.
90-24787

ACCESSORIES
W/STUDS

FROM

ANDERSON, HAROLD
PO BOX 171
100 ELDER RD
MANCELONA MI 49659

SHIP TO

ANDERSON, HAROLD
PO BOX 171
100 ELDER RD
MANCELONA MI 49659

ACCOUNT

ACCOUNT NUMBER A/C

059001

WRITE ☐

FROM DATE

9-28-90

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

WORK DONE

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARKED

CUSTOMER'S REQUEST

See attached letter

MAIN FAULT

Trigger assembly contaminated with gummy residue; internal parts not moving freely - rear safety cam is stuck to assembly side plate.

PARTS

91469 TRIGGER ASSEM.

The gun subject to N/A. recall - still has original trigger assembly

Install new trigger assembly at N/A. under recall.

9/26/90
JES

REPAIRMAN

BW

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

OCT 16 1990

RD4925 REV. 6/88