

January 17, 1986

*Mr. J.A. Stekl, Supervisor
Product Service Supervisor
Ilion, NY 13357*

Dear Sir:

Reference to your letter of December 23, 1985. I have thought about the problem with the 270 Model 700.

I believe the rifle fired when I raised the bolt handle a little; then realizing the bolt would not open until I released the safety. When the safety is released the rifle fires.

I bought the rifle new and it has not been worked on by anyone.

I am positive I did not have my finger on the trigger when I released the safety.

Sincerely,

Glen E. Anson
Glen E. Anson