

NOTE
CHECK GATE POSITION
ON PART. DNG. MUST BE ON
CORRECT SIDE.

STAMP MOLD 788 SAFETY BUTTON

NOTE (2) NEW CORES TO FIT INTERCHANGEABLE
WITH OLD CORES NEW SIZE ON WIDTH OF
LUGS ONLY WAS .055-860 NEW SIZE .080-075
JOB # 4460

FINAL DRAWING
FOR YOUR FILE



3-9-77

Back inserts for XP-100 safety button

MOLD ASSEMBLY		RD CAV.	4	TYPE	INJECTION
		CUST.	REMINGTON	PROD.	SAFETY BUTTON
		PRESS	65 H100 MINIJECTOR		
SCALE	DATE	DR	LR	APP.	
	7-23-65	W/P			
J. G. TILP, INC.				JOB NO.	
UNION, N. J.				6982	

FILED 6982 SAFETY
BUTTON


1-2




1.030
R2.0

DIA C.
1262
125-8 MEAN
125-4

DIA A
1608
1608





NOTE
CHECK GATE POSITION
ON PART. DNG. MUST BE ON
CORRECT SIDE.

STAMP MOLD 788 SAFETY BUTTON

NOTE (2) NEW CORES TO FIT INTERCHANGEABLE
WITH OLD CORES NEW SIZE ON WIDTH OF
CORES ONLY WAS .035-.060 NEW SIZE .000-.025
JOB # 4460

FINAL DRAWING
FOR YOUR FILE

3-9-77

Back inserts for XP-100 safety button

MOLD ASSEMBLY		NO. CAV.	4	TYPE	INJECTION
		CUST.	REMINGTON	PROD.	SAFETY BUTTON
		PRESS	65 H/100 MINISECTOR		
SCALE	DATE	DR.	LA.	APP.	
	7-23-65	2/12			
J. G. TILP, INC.				JOB NO.	
UNION, N. J.				6982	