Remington Arms Co., Inc. Liability Waiver

Date: 8/8/2007

Dear Mr. Norris

We have received the following firearm: <u>Model 700 204 Ruger caliber</u>; Serial number: <u>G6464942</u>.

We have examined your firearm and determined that the Fire Control Mechanism (Trigger Assembly) is in need of repair or replacement due to adjustments made outside the factory. In its current condition we feel that the rifle can not be operated in a safe manner and should not be used. As such, we recommended to you via repair #: 132264 that we replace the Trigger Assembly. We offer to install the new Trigger Assembly for a special price of \$50.00.

You have decided not to have us replace the Trigger Assembly but have requested it returned to you in its current state. We will return it with the firearm provided that you sign this document verifying that:

- You were presented with an opportunity to have the Trigger Assembly replaced.
- You understand that it is Remington's opinion that the firearm is currently not in a safe condition.
- You have been informed by Remington that the firearm should not be used until the Trigger Assembly is properly repaired or replaced by a Remington Authorized Repair Center or by Remington Arms Company, Inc.

Sign below:		
Customer's Name:		